



# INTAKE & VALVE COVER REPAIR KIT

## FIXES OIL-CONTAMINATED INTAKE MANIFOLDS

**615-177**  
Ford Windstar  
**(3.8L)**  
2003-99

**Almost 1 Million Ford Windstars  
Manufactured With this Defect!**



### PROBLEMS

- Check Engine Light
- Engine Misfire
- Lean Diagnostic Trouble Codes

### CAUSES

- Oil Contamination of Intake Due to Poor Valve Cover Design
- Vacuum Leak from Oil-Soaked Pressure Regulator Vacuum Line
- Vacuum Leak Between Upper & Lower Intake Due to Loss of Tension at Isolator Bolts

### DORMAN SOLUTION

- Multiple Problems / One Easy Fix
- Includes ALL Parts to Repair the Problem and Prevent Recurring Symptoms



Activant Path **Engine, Valve Cvr Repair Kit - Valve Train & Cyl Head Prts** Activant Code **DII**

For a Complete List of Applications, Visit Our Web Site: [www.DormanProducts.com](http://www.DormanProducts.com)



Ballwin ◦ Belleville ◦ Cahokia ◦ Dorsett ◦ Fairview Heights ◦ Granite City ◦ Maplewood ◦ St. Peters ◦ South County  
(636)227-9009 (618)277-8556 (618)332-2145 (314)994-0779 (618)277-2770 (618)451-9970 (314)647-7350 (636)447-9125 (314)631-3900

[www.alsautomotive.com](http://www.alsautomotive.com)